## Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE \_\_yes \_\_no

1. Nan	1e (indicate pr	referred name)		· · · · · · · · · · · · · · · · · · ·
historic	HILLARY-MAIN HOUS	SE		
and/or common	MAIN'S GREENHOUSE	3		
2. Loca	ation			
street & number	, 3659 RIVA ROAD			not for publication
city, town	DAVIDSONVILLE	vicinity of 4th	congressional district	, and a second
state	MARYLAND	county	ANNE ARUNDEL	
3. Clas	sification			
Category  district: X building(s) structure site object	Ownership  X public private both Public Acquisition in process being considered x not applicable	Status  X occupied  unoccupied  work in progress  Accessible  yes: restricted  yes: unrestricted  no	Present Use  X agriculture Commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
<u>4. Own</u>	er of Prope	rty (give names and	d mailing addresses	of <u>all</u> owners)
name	WILLIAM P STEPHENS	S & HILDA S STEPHENS		
street & number	40 CORNHILL STRE	EET	telephone no	·: 263-3118
city, town	ANNAPOLIS	state a	nd din and	1401
5. Loca	ation of Leg	al Descriptio		
courthouse, regis	stry of deeds, etc.	ANNE ARUNDEL COUNTY	COURTHOUSE	liber 3356
street & number	SOUTH STREET			folio 709
city, town	ANNAPOLIS		state	MD 21401
6. Repr	esentation	in Existing	Historical Surve	eys
itle				
Įate			federal state	county loca
epository for sur	rvey records			county local
ity, town			state	

## 7. Description

Survey No. AA-847

excellent deteriorated	heck one unalteredX_ original site X_ altered moved da	te of move
------------------------	--	------------

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

A one and one-half-story gable house with lap siding is located 1/8th mile north of Route 214 on the east side of Riva Road. The house faces west and sits back about 150 feet from the road. Two small poly-greenhouses are located north of the house. There is a small plank shed in the rear yard. The main section of the house has an asphalt-shingle gable roof with plain box cornices. The front door, which is located in the center, has a glass sash in the upper half. Its lower section has three panels, with the top panel divided and the lower two horizontal.

Centered in the front of the main section, there is a porch with a hip roof. The porch ceiling has narrow groove boards and the flooring is plain and narrow.

On either side of the front door are two-over-two windows with vertical panes. In the roof of the main section, centered over the front door, is a gabled dormer with a one-over-six window.

A wing with a hip roof has been added to the north side of the house. It is centered below a two-over-two window in the gable. There are windows abutting the wing on the first floor which have two-over-two vertical panes.

Between the first floor two-over-two window, there is an ell, built in two periods. The earlier addition has a hip roof (whereas the later portion has a shed roof). In this earlier section, there is a small six-over-one window on the north and a two-over-two window to the south, similar to the main structure. The newer section has paired eight-pane casement windows on the north side. The rear has two sets of similar casements set in side-by-side, with a five-panel back door on the left. A narrow cinder block chimney is located close to the junction of the south side of the ell and the main house.

Another wing has been added to the south end of the house. On the front, it is flush with the original house, but covers only two-thirds of its sides and abuts a two-over-two window on the east. The rear and the front of the wing have triple windows with six-over-one sash. The end has a brick chimney centered in the gable and, on each side, six-over-one windows. The second floor of the main house has a two-over-two window centered in the gable.

The cellar is partially dug out. It is reached by a bulkhead located on the northeast corner of the house. The portion under the main house is lined by cinder block areas, whereas under the ell there is poured concrete. The center cross beam and the joists are circular sawn. The center beam is also reinforced by an eight-by-eight beam. The foundation of the entire structure is constructed of an assortment of wood, cinder block, poured concrete, and red tile.

Inside, a narrow center hall separates paired rooms on each side. The parlor side has a wall which is divided by a waist-high wall (passageway) with two supporting decorative columns. The wall opens to the dining room. On the north side of the center hall are two similar size rooms. Both have access to the north wing. Throughout these areas, the trim is made of plain boards with simple corner blocks. The baseboards are plain with a quarter round toe molding. All interior doors have five horizontal panels except for a pair of French doors which lead to the south

0. 3	riginiteance	Survey No. AA-847	
Period	—1499       archeology-historic       conservation         —1599       agriculture       economics         —1699       architecture       education         —1799       art       engineering         —1899       commerce       exploration/settlem	ng landscape architecture religion science sculpture social/ music humanitarian	
Specific	dates Builder/Architect		
check:	Applicable Criteria: _A B _C _D and/or Applicable Exception: _A B _C _D	E _F _G	
	Level of Significance:nationalstate	local	
Prepare support	both a summary paragraph of significance and	d a general statement of history and	

The Hillary-Main House is a 1½ story frame house that appears to date to the mid- to late-19th century. The original section is two rooms deep with a center passage plan; later additions have been made to both gable ends and the the rear facade.

## 9. Major Bibliographical References

Survey No. AA-847

DEED 3356-709
DEED 2912-473 11/24/1976
DEED 2766-848 6/26/1975
DEED WGL 2705-81 9/12/1974

DEED WNW 13-111 2/27/1919 WILL OBD 2-152 1919

MD 21035

state

10. Geographi	cal Data			
Acreage of nominated property  Quadrangle name  UTM References do NOT com			Quadrangle scale	
A Zone Easting No	orthing	B Zone	ne Easting Northing	
C		D F H		
Verbal boundary description	and justification			
List all states and counties	or properties overl	apping state or	or county boundaries	
state	code	county	code	
state	code	county	code	
11. Form Prep	ared By			
name/title DAVIDSONVILLE H	ISTORIC SURVEY	PEAM		
organization DAVIDSONVILL	E AREA CIVIC ASS	SOCIATION	date 4/4/1987	
street & number 985 ST.	GEORGE BARBER RO	)AD	telephone 798-6145	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

DAVIDSONVILLE

city or town

Maryland Historical Trust

Shaw House

21 State Circle Annapolis, Maryland 21401

(301) 269-2438

wing. The newer south wing has a fireplace which has been converted to a woodstove. The walls are knotty pine and the ceiling has exposed beams. The floors are finished in three-and-one-half-inch-wide oak.

The kitchen is reached by a door to the ell, on the east side of the dining area. On the north wall is a door to a closet which is set under the ladder-like stairs. The ladder stairs lead to a very large open room which fills the attic space of the main house.

